
Northchurch, Berko, – Location Report

New Road **Rejected**

What3words /// surgical.expensive.trooper

(Nearest postcode: HP23 5QE)

The entrance to Northchurch upper allotments and Sunnyside Rural Trust – Location visibility insufficient to allow SID sign to detect approaching vehicles travelling northeast along New Road. This is due to heave vegetation along the edge of the roadway with no footpath. The entrance to the allotments is not suitable for the volunteers or equipment to be housed safely and will cause an obstruction to road users view of adjoining and leaving the allotments.




New Road Rejected

What3words /// compose.storage.laminate

(Nearest postcode: HP23 5QE)

The junction of Bridgewater Hill – Location visibility sufficient to allow SID sign to detect approaching vehicles travelling southwest down New Road. However, there is a fixed SID sign approximately 50yrds away from the location and could cause conflicting readings between the two SIDs. This location is also within the 161 mts away from the 40mph zone and will pick up vehicles outside of the 30mph zone. This location will also not allow road users an unobstructed view of adjoining New Road from Bridgewater Hill. The footway is not sufficiently wide enough to provide a minimum of 1.0 mtr clear and unobstructed footway width.



Photos taken whilst on sight visit














YOUR SPEED
mph

